


<b>CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM</b>		Page 1 of 3
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 08/27/2008
Test Type: Smoke	Ground Condition: Dry: <input checked="" type="checkbox"/> Damp: <input type="checkbox"/> Wet: <input type="checkbox"/>	Supervisor: E.R. Crew: 04
Manhole ID: S19K__048MH	Test ID: 1029-567	Notifications Made: <input type="checkbox"/> X <input type="checkbox"/> Residents, Fire, 311
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)		



[illegible]

**CITY OF BALTIMORE**  
**SMOKE TESTING OBSERVATION SUMMARY**  
**LOW LEVEL SEWERSHED**  
BALTIMORE CITY PROJECT 1029  
REI/DRAYCO

Unique Test ID: 567	Date: 08/27/2008	Basin: LL - 44	Manhole ID: S19K__048MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 2022 RAMSAY ST.			
Source Type: 03 Cleanout	Sector: 02 Private		
Location: 08 Yard - Back	Severity: 03 Moderate	Drainage Area: 0	
Comments: ABOVE GRADE CLEANOUT IN BACKYARD WITHOUT CAP.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01  
Filename: 1029-567\_OB01-01.jpg